



ENGLISH TRANSLATION
(Original in Punjabi)

OFFICE: EXECUTIVE ENGINEER, PROVINCIAL DIVISION, PUBLIC WORKS DEPARTMENT, BUILDINGS
& ROADS, BRANCH MANSA

Telephone/Fax No 01652-232119

Email ID: xen manasigmail.com

Letter No. 2005

Date 01/07/2026

To

Principal

S. Chetan Singh Sarvhitkari Sr.Sec. Vidya Mandir, Mansa

Sub:- Regarding issuance of building safety Certificate (year 2026-27).

Ref :- Regarding yours letter No.SVM/32/2026-27 dated 25.05.2026.

Visual inspection of your school building was conducted by the office of Sub Divisional Engineer. As per their report/ recommendation school building safety certificate for the year 2026-27 till 31.03.2027 is issued on the basis of following inspections and terms and conditions: -

1. On 14.05.2026, Structure Safety Certificate has been issued by Er. Kulwinder Singh and as per his certificate, the school is safe for use for the session 2026-27 but this school has not been constructed by this department, so safety of school structure cannot be made ensure by this department particularly from earthquake angle.
2. In case addition, alteration, extension and emendation is needed by the school or to be made, then immediate inspection from this office should be managed and safety certificate of that portion be obtained from this office again after completion.
3. In case the walls, foundations and roofs of building are in deplorable condition due to natural calamity or any other reason, this office be informed immediately by the school about the condition of the building and building be used after getting its inspection.
4. Fire Safety Certificate and Electricity Safety Certificate be obtained separately from the concerned department.
5. Keeping in view priority of safety of school building, it is responsibility of school management to get the building repaired. In spite of this report, school management is responsible for the safety of school management is responsible for the safety of school building in all respects.
6. The school should have plan to tackle with any untoward incident including plan of turning out the students safe from the school building during emergency and the concerned department. To make ensure this plan effective, it is necessary to review and update it regularly.




7. As per Punjab Government instructions, school management is solely responsible to get approval of road to access from the concerned department.

8. Staff members should be given proper safety training by the school including to take care in emergency, activities of first aid and exit protocol.

9. A sum of Rs.15,000/- in words rupees fifteen thousand received vide G.R.No.4629235 dated 02.06.2026 as building inspection fee as per covered area of school.

10. This report is not valid for legal purpose.


Encl: Site plan



Sd/-

Executive Engineer,
Provincial Division B & R Branch
Mansa
Dated:

A copy of the above is sent to Sub Divisional Engineer Provincial Division No.1 B & R Branch Mansa in connection with his letter No.69 dated 22.05.2025 and written that keeping in view of your recommendation, building safety certificate is issued to the school



Sd/-

Executive Engineer,
Provincial Division B & R Branch
Mansa
Dated:

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

1. Name of The School : Sardar Chetan Singh Sarv Hitkari, Sr.Secondary, Vidya Mandir
2. Location : Jagdambe Road Mansa
3. Plot Area : 94807.98 Sqft or 2.1765 Acres
4. Plinth Area : i) Gr.Floor-28000.725 Sqft
ii) 1st Fl.-28404 Sqft
iii) 2nd Floor-19963.77Sqft

Total Covered Area=76388 Sqft

5. No. of Storeys : 3 Storeys
6. Year of Construction of Building : 1982-2021
7. If the Building has been : No
Constructed under the supervision
Of the qualified engineer, the following
Details may be given
- a) Name of the Engineer with qualification : NA

- b) Address of the engineer : NA

- c) Set of Structural drawings used in the Construction, if available
- d) Name & Address of Architect with qualification :

8. Whether the building has been constructed for
The purpose of

- a) School Yes
- b) Residential Purpose & Converted for use as School No

9. Materials used for roofs

- a) RCC Slabs Yes
- b) R.S.Joists And Beams No.
- c) Wooden Joist & Battens No
- d) Arch (Brick) No.

10. Materials used for Walls :

- a) Mud Mortar No
- b) Cement Sand Mortar Yes

11. Plaster:

- a) Lime Mortar No
- b) Cement Mortar Yes


12. Flooring


- a) Conglomerate Tiles+Conglomerate
- b) Terrazo Yes/No
- c) Brick Paving

13. A detailed drawing indicating dimensions of rooms
Along with size and location of Doors/ Windows



Principal
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916


Principal
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916






FIRST FLOOR PLAN



SECOND FLOOR PLAN

COVERED CORRIDOR 12X105'

Sub Divisional Engineer
 Provl. Sub Divn. No. 1 PWD (B&H)
 Mansa



FIRST FLOOR PLAN

S. Chetan Singh Sarvhitkari Sr. Sec.
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir Mansa

S. Chetan Singh Sarvhitkari Sr. Sec.
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916

S. Chetan Singh Sarvhitkari Sr. Sec.
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916

Bharat Bhushan Bansal Associates
Er. Bharat Bhushan Bansal
Er. Kulwinder Singh
Approved M.C. MANSA
Vide Order No. 489, Dt. 06-01-1986

1ST FLOOR PLAN

VIDYA BHARTI EDUCATIONAL TRUST

Specification's

- 1 Spread Footing Foundation With Base Conc 1:8:16
- 2 B/W in Foundation Up to Plinth in Lime Mortar
- 3 1st Class With in Super Structure With C.S Mortar 1:6
- 4 R.C.C / R.B.C Slab
- 5 C.S Plaster on Walls & Ceiling
- 6 Tile Terracing
- 7 Wood Work / Iron Work In Joinery
- 8 Conglomerate Flooring 1:2:4
- 9 D.P.C 1:2:4 In C.Con With Two Coats of Hot Bitumen

Details of Joinery

Size	Sill Level	No.
D= 4'0" x 7'0"	0'0"	27+30+15
D1= 3'0" x 7'0"	0'0"	3 + 1 + 3
D2= 2'6" x 7'0"	0'0"	14+15+13
D3= 3'6" x 7'0"	0'0"	1
W= 4'9" x 4'0"	3'0"	19+29+7
W1= 4'0" x 4'0"	3'0"	48+44+20
W2= 5'0" x As Per Site		0 + 1 + 1
W3= 3'6" x 4'0"	2'6"	1
W4= 3'0" x 3'3"	3'9"	2
V= 3'0" x 3'0"	5'0"	4 + 3 + 2
V1= 1'6" x 1'6"	6'6"	16+16+10

Area Statement

Total Area OF Land=94807.98Sqft or 10534Sqyd=2 1765 acre
Ground Floor Covered Area =28000.725Sqft
First Floor Covered =28424.41 Sqft
Second Floor Covered Area = 19963.77 Sqft
Total Covered Area=76388.905sqft
Play Ground Area= 51027Sqft

Sign. Of Owner

Symbol

FIRE EXTINGUISHER



FIRE ALARM



SAND BUCKET



FIRE HOSE



Sign. Of Architect

S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916

Sub Divisional Engineer,
Provl. Sub Divn. No.1 PWD (B&R)
Mansa

S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, Mansa
(Affi. to C.B.S.E) Affi. No. 1630927
School Code: 20916

Bharat Bhushan Bansal Associates
Er. Bharat Bhushan Bansal
Er. Kulwinder Singh
Approved M.C. MANSA
Vide Order No. 489, Dt. 06-01-1986