

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰਬਰ 1, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਦੂਜੀ ਮੰਜ਼ਿਲ, ਬਲਾਕ-2, ਜ਼ਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ, ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,
ਸੰਤ ਈਸ਼ਰ ਸਿੰਘ ਪਬਲਿਕ ਸਕੂਲ
ਫਾਰਜ਼ ਜ਼ਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰ: 168

ਮਿਤੀ: 18-06-2024

ਵਿਸ਼ਾ:- ਸੰਤ ਈਸ਼ਰ ਸਿੰਘ ਪਬਲਿਕ ਸਕੂਲ ਫਾਰਜ਼ ਜ਼ਿਲ੍ਹਾ ਸੰਗਰੂਰ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਬਾਰੇ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਮੁਆਇਨਾ ਕਰਨ ਉਪਰੰਤ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨੱਥੀ ਪ੍ਰੋਫਾਰਮੇ ਤੇ ਬਣਾ ਕੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ। ਸਕੂਲ ਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਜੀ.ਆਰ. ਨੰ: 674348 ਮਿਤੀ 18-06-2024 ਰਾਹੀਂ ਬਾਬਤ ਰੁਪਏ 10,000/- ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ / ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 10606 ਮਿਤੀ 28.03.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

4749-6/13-20,000x100-Pb. Govt. Press, Patiala

(Provincial)

Serial No. Y 674348
18-06-2024

Received from ਸੰਤ ਈਸ਼ਰ ਸਿੰਘ ਪਬਲਿਕ ਸਕੂਲ
ਫਾਰਜ਼ ਜ਼ਿਲ੍ਹਾ ਸੰਗਰੂਰ

with letter No. dated 18-06-2024

the sum of Rupees 10,000/-

in Cash/by Cheque on account of ਸੰਤ ਈਸ਼ਰ ਸਿੰਘ ਪਬਲਿਕ ਸਕੂਲ

in payment of

Rs. Signature
Sub Divisional Engineer

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

Part-II

Building Safety Report

Name of School: Sant Ishar Singh Public School, Village-Chhahar, Tehsil-Sunam, Distt. Sangrur.

I have visited the above-mentioned School Building along with Sh. Manish Kumar, Junior Engineer and on visually inspection, it seems safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Govt. Policy No. 05/13/2018-3BR3/1294287/3 dated 10-08-2018.
- j) The building visually seems safe to occupy for normal use to **One Year, upto 31.03.2025.**

Sub Divisional Engineer
Const. Sub Divn. No. 1, PWD. B&R
Sangrur.

Manish
J E