



ਦਫਤਰ : ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ
ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।



ਈਮੇਲ : xenpwbarnala@yahoo.com

ਦੇਸ਼,

ਪ੍ਰਿੰਸੀਪਲ,

ਬਰੋਡਵੇਅ ਪਬਲਿਕ ਸਕੂਲ,

ਮਨਾਲ, ਜ਼ਿਲ੍ਹਾ ਬਰਨਾਲਾ।

ਨੰਬਰ... 66

ਮਿਤੀ: 05/06/2026

ਵਿਸ਼ਾ:-

ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:-

ਆਪ ਦੇ ਸਕੂਲ ਦਾ ਪਤਰ ਨੰਬਰ BPS-100/26-27 ਮਿਤੀ 13-05-2026 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲੇ ਅਧੀਨ ਪਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਹਵਾਲੇ ਅਧੀਨ ਨਵੀਂ ਬਿਲਡਿੰਗ ਦੇ ਨਵੇਂ ਮੁਤਾਬਿਕ ਸਬੰਧਤ ਜ਼ਰੂਰੀਆਂ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਵਿਸ਼ਾ ਅੰਕਿਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਸਾਈਟ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਕੀਤੀ ਗਈ ਸਿਫਾਰਸ਼ ਅਤੇ ਮੰਡਲ ਦਫਤਰ ਵੱਲੋਂ ਜੀ.ਆਰ.ਨੰਬਰ 931583, ਮਿਤੀ 02/06/2026 ਰਾਹੀਂ 20,000/- ਰੁਪਏ ਦੀ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਫੀਸ ਅਨੁਸਾਰ ਆਪ ਨੂੰ ਸਾਲ 2026-27 (ਮਿਤੀ:31/03/2027 ਤੱਕ) ਦੇ ਸਮੇਂ ਦੀ ਮਿਆਦ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਅਨੁਸਾਰ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

- This building safety certificate is issued as per visual inspection and seems safe to occupy for the normal use up to 31-03-2027.
But parameters to check the actual stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports, certificate from Engineer in Charge for construction etc. are not available.
- In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building. It is assured that no stagnant water is on roof of building.
- A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Works should be obtained from the competent authority.
- The owner of the building/ Management is fully responsible regarding safety of building from all angles in spite of this report.
- The covered area of the building is 100142 Sq.ft.
- This Report is not valid for legal purpose.
- The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Government policy No. PWDCEH-11012/56/2022-6BR3/2977 Dated, Chandigarh 03.08.2023.
- Any other guidelines as required or amended by the Govt. should be fulfilled & followed from time to time.

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।

ਮਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਰਾ ਧਾਰਜਯਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ. (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਬਰਨਾਲਾ ਜੋ ਨੂੰ
ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਮਿੱਠ ਅੰਕਣ ਨੰਬਰ 1028 ਮਿਤੀ 21-05-2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਮਿੱਤਰ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੋ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਬਰਨਾਲਾ।

Principal
Broadway Public School
Manal, Barnala (PB.)

BROADWAY PUBLIC SCHOOL
Manal, Barnala (Pb.)

Director/Manager

TRUE TRANSLATION FROM PUNJABI TO ENGLISH

Office: Sub-Divisional Engineer, Provincial Sub-Division, Public Works Department
Building and Roads Branch, Barnala

LOGO

Email : xenpwwbarnala@yahoo.com

LOGO

To,
Principal,
Broadway Public School,
Manal Distt. Barnala
No. 66

Date:-05/06/2026



Subject: Regarding issuance of building safety certificate.

Reference :- Regarding your Letter No. BPS-100/26-27 date 13-05-2026

It is written regarding the above mentioned subject and reference letter that as per the building plan attached under reference, by the inspection and approval of Junior Engineer and fee of rupees 20,000/- (rupees twenty thousand only) vide Receipt No. 971583 dated 02.06.2026 deposited by Sub Division, the Building Safety Certificate for the period of year 2026-2027 (upto 31.03.2027) is issued as per the conditions mentioned below:

- This building safety certificate is issued as per visual inspection and seems safe to occupy for the normal use up to 31-03-2027.
- But parameters to check the actual stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawing, Technical Specifications, Test Reports of Material used, Quality Control reports, certificate from Engineer in Charge for construction etc. are not available.
- In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- In case the building is affected by flood or if there is settlement of walls/foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of building. It is assured that no stagnant water is on roof of building.
- A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Works should be obtained from the competent authority.
- The owner of the building/ Management is fully responsible regarding safety of building from all angles in spite of this report.
- The covered area of the building is 100142 Sq.ft.
- This Report is not valid for legal purpose.
- The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as Government policy No. PWCDEH-11012/56/2022-6BR3/2977 Dated, Chandigarh 03.08.2023.
- Any other guidelines as required or amended by the Govt. should be fulfilled & followed from time to time.

Sub Divisional Engineer,
Provincial Sub-Division, P.W.D.
Bh & M Branch, Barnala.

Number:

Date:

A copy of the above is sent to the Executive Engineer, Construction Division, P.W.D. Bh & M Branch Barnala for information regarding this office reference number 1028 dated 21-05-2026.

TRUE, TRANSLATION FROM
Punjabi, Hindi Urdu to English

NOTARY PUBLIC
BARNALA (Pb.) INDIA

Sub Divisional Engineer,
Provincial Sub-Division, P.W.D.
Bh & M Branch, Barnala.

Principal
Broadway Public School
Manal, Barnala (PB.)

BROADWAY PUBLIC SCHOOL
Manal, Barnala (Pb.)

Director/Manager